

FOG FREE

Anti-fog treatment for glass and plastic surfaces.
Invisible and smell-free, it leaves no traces on the surface.

CHARACTERISTICS

Base: water
Relative density: 1,00 g/cm³ ± 0,05
Color: clear

SUBSTRATE PREPARATION

For excellent results, it is recommended to apply on clean and degreased surfaces.
Gelson suggests the use of specific SET UP detergent and a HITEK cloth.

APPLICATION

Ready to use product.
Spray the product directly on the surface. Spread it evenly using a HITEK cloth.
Let it dry for a few minutes.
Remove excess product and eliminate streaks with a green microfiber cloth.

The product needs to be applied again every time the glass is washed.

The effectiveness of our products is based on practical experiences and research work carried out in our laboratories; nevertheless we accept no liability for work carried out following our instructions being clear that the final result depends in all cases on a series of unforeseeable factors.

* For any information about product codes or packs, please see our catalogue, our price list or contact us.